

UTTERMOST V TNSTRUCTION


		ASSEMBLY		CTIC		90	
			PART				
0 [RAWING	PARTS NAME	Q'TY,	NO	PARTS NAME	DRAWING	QTY
A	0	FLATI WASHER 5/16"*3/4"	8PCS	1	SEAT ASSEMBLY		1PC
В	©	LOCK WASHER 5/16"	8PCS	' 2	LEFT LEG	♦	1PC
С	9500	BOLTS DIA 5/16"*2"	4PCS	3	RIGHT LEG	\$	1PC
D)em	BOLTS DIA 5/16"*3"	4PCS	5	SEAT FRAME CAPRAIL		1PC
Е		ALLEN WRENCH 5/16"	1PC	6	FRONT RAI		1PC
F	8	SCREW #8*2"	6PCS	_			1PC
G	8200	SCREW #8*3/4"	4PCS	7	BACK RAIL		
ASSEMBLY BOLTS MAY NEED TIGHTEND AFTER USE							
			3		TEP 4		
211	EP 3	A B D D D D D D D D D D D D D D D D D D	y		TEI 4		F•4

PO BOX 558/3325 GRASSY HILL RD.ROCKY MOUNT ,VIRGINIA 24151 WWW.UTTERMOST.COM



ASSEMBLY INSTRUCTION

ITEM: 23390



To avoid wobbly product and gaps between legs and stretchers, please follow below steps to assemble:

- 1) Attach the legs. Do not completely tighten the bolts that hold the legs.
- 2) Attached the stretchers. Completely tighten the screws that hold the stretchers.
- 3) Set the chair on the floor to level and then finish tightening the leg bolts