


 **SCHONBEK** | 1870










CHANTANT
CH1813N- __ __ O








THIS DESIGN IS THE PROPRIETARY
TRADE DRESS/TRADEMARK OF
W SCHONBEK LLC.

5 Lights
Diameter: 21"
Height: 70-1/4"
Hanging Weight: 45-1/2lbs.


 **SCHONBEK** | 1870

| | | | | | | | | |
|---|---|---|----------|---|---|---|---|---|
|  |  |  | S |  |  |  |  |  |
| MAX 50 W | 110-120 V |  | | | | | | |






1 X  : 1746










1746



3




4






5 X  : GU10 50W MAX 




11

12




- 13 A1 - A7
- 14 B1 - B10
- 15 C1 - C5
- 16 D1 - D18
- 17 E1 - E22
- 18 F1 - F24
- 19 G1 - G32



After hanging all trim, remove labels from crystals. If residue remains, wipe off crystal with a soft, dry cloth.

 **SCHONBEK** | 1870










CHANTANT
CH1813N- __ __ R








THIS DESIGN IS THE PROPRIETARY
TRADE DRESS/TRADEMARK OF
W SCHONBEK LLC.

5 Lights
Diameter: 21"
Height: 70-1/4"
Hanging Weight: 45-1/2lbs.


 **SCHONBEK** | 1870

| | | | | | | | | |
|---|---|---|----------|---|---|---|---|---|
|  |  |  | S |  |  |  |  |  |
| MAX 50 W | 110-120 V |  | | | | | | |












1 X  : 1746








1746








5 X  : GU10 50W MAX 



- 13** A1 - A7
- 14** B1 - B10
- 15** C1 - C5
- 16** D1 - D18
- 17** E1 - E22
- 18** F1 - F24
- 19** G1 - G32



After hanging all trim, remove labels from crystals. If residue remains, wipe off crystal with a soft, dry cloth.