


ASSEMBLY AND INSTALLATION INSTRUCTIONS

WARNING: TO AVOID RISK OF ELECTRICAL SHOCK, BE SURE TO SHUT OFF POWER PRIOR TO INSTALLING OR SERVICING THIS FIXTURE.

NOTE: Before installing, consult local electrical codes for wiring and grounding requirements.



Installation Steps

1. Carefully unpack your new fixture and lay out all the parts on a clean surface. Take care not to lose any small parts necessary for installation.
2. Remove the two fixture housing screws to release the mounting plate. Remove mounting plate from fixture.
3. Place driver in j-box. Be sure to leave the orange connector accessible.
4. Make wire connections from j-box to driver. Refer to driver label for wire identification.
 - **FOR DIMMING:** If using a dimmer (not included), follow wiring instructions enclosed with dimmer. Note: For phase dimming, cap off gray and purple wires as they are only used for 0-10V dimming. Double check wiring. Tuck the wire connections neatly into the junction box.
 - **FOR NON-DIMMING:** If not using a dimming switch, with wire nuts, cap off purple and gray wires individually. Connect neutral (white) wire with neutral wire, hot (black) wire with hot wire. Double check wiring. Tuck the wire connections neatly into the junction box.
5. Feed orange connector from driver through center hole in mounting strap, and secure mounting strap to the j-box using j-box screws.
6. Secure backplate and mounting plate to the mounting strap. Be sure to keep both pieces level.
Note: If mounting to a 4" square box with mud ring, do not use the mounting strap. Secure the mounting plate directly to the mud ring.
7. Connect the orange connectors together, and attach the fixture to the mounting plate with the fixture screws.
8. Turn power back on at fuse or circuit box.

OXYGEN LIGHTING ©

oxygen

OXYGEN LIGHTING
201 RAILHEAD RD, FORT WORTH, TX 76106
TEL. (877) 607-0202 FAX (877) 607-0203
WWW.OXYGENLIGHTING.COM

ASSEMBLY INSTRUCTIONS

ZENITH sconce
3-556-xx