



ASSEMBLY INSTRUCTIONS

1. Carefully unpack and identify all parts referring to illustration for parts identification.
2. Turn the power to the installation point OFF.
3. Attach the crossbar bracket (B) to the junction box and secure it by using the two screws (C). The side of the crossbar bracket marked "GND" must face outside.
4. Using the wire connectors (A) provided to connect fixture wires and supply wires: black to black, white to white, and ground to copper/bare.
5. Place the canopy (D) over the crossbar (B) and secure with the ring nut (E).
6. Secure the metal loop (F) onto the nipple of the body (H).
7. Connect the metal loop (F) and the chain (G) together, then thread them into the canopy (D).
8. Install the shades (I) onto the sockets, securing them with socket rings (J).
9. Install proper bulbs (K) (not included) into the sockets, referring to the markings and/or labels on the fixture for maximum wattage.
10. Restore power to the installation point and retain this sheet for future reference.