

UTTERMOST


Assembly Instruction

STYLE:04038

PART LIST

CI DIOI	
METAL PANEL	2PCS
SUPPORT POLE	4PCS
GLASS	4PCS
	METAL PANEL SUPPORT POLE

Allen Head Bolts	16PCS
Allen Wrench	1PC
SUCTION CUP	16PCS



- Take the parts carefully out of the carton, and then place them on a soft and flat surface, making sure that the parts will not be damaged.
- 2 Separately use the allen head bolts to fix Metal panels(A) with Support poles(B) together, then use the Allen Wrench to secure all the Allen Head Bolts.
- 3. Carefully insert Glass(C) through the middle parts of the Metal paneis(A), make sure the Glass(C) sit firmly on the Suction cups which installed on the Metal panels(A) yet. Then hang this on the wall with anchors and screws. Assemble is completed.

To clean, use a dry soft cloth.

pls strictly assemble this item according to location labels in the same color.

PO BOX 558/3325 GRASSY HILL RD. ROCKY MOUNT, VIRGINIA 24151 www.uttermost.com